

WIRING DIAGRAM EXAMPLE FOR HEATER CIRCUIT

MATERIALS NEEDED:

- 1 - 6" x 6" x 3" BOX WITH HINGED LID
- 1 - CONTACTOR - WHITE RIDGES / RBM #90-244
- 1 - MACHINE TOOL TRANSFORMER 480 x 24 VOLT
- 1 - PANEL MOUNT FUSE HOLDER (480 V RATED) 2 AMP FUSE

Fuse, 2amp, 480 volt rated

